



REMSA INC.
Research, Environmental & Management Support

Date: ^{wed} 05 June 02

Location: Lat/Long 40° 30.609 73° 57.813 Vessel: SAND MASTER / SANDY HOOK
TUG HOPPER BARGE

Weather Conditions: Partly Cloudy - 70°F

Water Temperature: Surface 60.5° F Below Midwater:

Condition of screening apparatus: draghead inflow screening (app. 2"x2")

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc):
draghead screening 2x2 ~ inflow

* Left Dock at 1145 AM

Observer's Name: TRISH BARCO

Observer's Signature: Pat D. Barger

Bridge Watch Summary

[illegible]



Thuv

Geographic Site: AMBROSE CHANNEL

Location: Lat/Long _____ Vessel: SANDMASTER

Weather Conditions: BEAUFORT 5 - windy - RAIN

Water Temperature: Surface 60°F Below Midwater:


Condition of screening apparatus: GOOD

Incidents involving endangered or threatened species? (Circle) YES ☐ NO ☒

Comments (type of material, biological specimens, unusual circumstances, etc):

NO DREDGING DONE - REPAIRS TO
DREDGE AND BAD WEATHER

Observer's Name: TRISH BARGO

Observer's Signature: 

Bridge Watch Summary

[illegible]

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: Fri 07 JUNE 02

Geographic Site: AMBROSE CHANNEL

Location: Lat/Long _____ Vessel: DREDGE SANDMASTER

Weather Conditions: WINDY - RAIN - PARTLY SUNNY - BEAUFORT 7

Water Temperature: Surface 59.5°F Below Midwater: _____

Condition of screening apparatus: GOOD

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

NO DREDGING - ROUGH WEATHER

Observer's Name: TRISH BARGO

Observer's Signature: *Trish Bargo*

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Saturday
Date: 06 JUNE 02

Geographic Site: AMBROSE CHANNEL

Location: Lat/Long 40° 31.394 13° 59.961 Vessel: DREDGE SANDMASTER

Weather Conditions: SUNNY - BEAUFORT 4

Water Temperature: Surface 59.5°F Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____


- NONE -

Observer's Name: Irish Bangs

Observer's Signature: _____

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.
Research, Environmental & Management Support

Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Sunday
Date: 09 JUN 02 - 1500 hrs

Geographic Site: AMBROSE CHANNEL, NJ

Location: Lat/Long _____ Vessel: DREDGE SANDY HOOK

Weather Conditions: SUNNY - 90°F Beaufort 2

Water Temperature: Surface 61°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

- NONE -

Observer's Name: Trish Bango

Observer's Signature: Trish Bango

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
<u>/</u>	<u>/</u>	<u>/</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 10 June 02 (0800 hrs)

Geographic Site: Ambrose Channel, NJ

Location: Lat/Long _____

Vessel: Dredge Sandy Hook
Tug Sandmaster

Weather Conditions: Sunny 70-80°F

Water Temperature: Surface 59°F

Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES

NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

~ departure delayed ~ ship traffic ~ LNG

~ arrival at dock app. 1800 hrs

Observer's Name: Trish Bargo

Observer's Signature: Trish Bargo

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 24 June 02

Geographic Site: Ambrose Channel

Location: Lat/Long _____

Vessel: Dredge Sandmaster

Weather Conditions: Partly cloudy

Water Temperature: Surface 65°F

Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

2-4 stone crabs
10 shark eye snails

Observer's Name: Trish Bargo

Observer's Signature: Trish Bargo

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 02 July 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°31.394 73°59.961 Vessel: Bridge Sandmaster

Weather Conditions: Partly cloudy with slight fog, Hot - 95°F

Water Temperature: Surface 70°F Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc):
mechanical breakdown (electric) caused delays in departure.

Observer's Name: TARA Fitzpatrick

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 03 July 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°31.391 73°59.961 Vessel: Bridge Sandmaster

Weather Conditions: Beaufort 3, Sunny 97°F

Water Temperature: Surface 70°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

1 - Clearnose Skate


5-8 hard clams.

Observer's Name: TARA FITZPATRICK

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 07 July 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°31.394 73°59.961 Vessel: Bridge Landmaster

Weather Conditions: Beaufort 3, Sunny 96°F

Water Temperature: Surface 70°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☐ NO ☒

Comments (type of material, biological specimens, unusual circumstances, etc): _____


1 - Clearnose Skate
1 - Knobbed whelk
1 - Shark eye

Observer's Name: Tara Fitzpatrick

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 05 July 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°31.394 73°59.961 Vessel: Bridge Sundmaster

Weather Conditions: Beaufort 4, Sunny & Breezy 82°F

Water Temperature: Surface 70°F Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____


3 - Unarmed Skates
1 - Knobbed whelk
1 - Sea Robin

Observer's Name: TARA Fitzpatrick

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>3</u>	<u>3</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 16 July 02

Geographic Site: Ambrose Channel

Location: Lat/Long 10°31.394 N 73°59.961 W Vessel: Bridge Tendermaster

Weather Conditions: Blauport 3 hazy - 83°F

Water Temperature: Surface 72°F Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

1- Shark eye

1- Hermit crab

Observer's Name: TARA FITZPATRICK

Observer's Signature: [Signature]

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 16 July 02

Geographic Site: Ambrose channel

Location: Lat/Long 40°30.05' x 73°56.53' Vessel: tugboat: sand master
Dredge Sandyhook

Weather Conditions: 2ft 16 KNOTS North clear warm

Water Temperature: Surface 72°F Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES **(NO)**

Comments (type of material, biological specimens, unusual circumstances, etc): _____

draghead & rocks, 1 stone crab

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 17 July 02

Geographic Site: Ambrose channel

Location: Lat/Long 40° 29.8' x 73° 56.08' Vessel: hip boat: sand master

Weather Conditions: from Sandy Hook at 14:43 High Tide 5-10 Knots → 10-15 Knots SW (by evening)

Water Temperature: Surface _____ Below Midwater: _____

Condition of screening apparatus: GOOD

Incidents involving endangered or threatened species? (Circle) YES ☐ **NO** ☒

Comments (type of material, biological specimens, unusual circumstances, etc): _____


dragged: rocks

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.

Records, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 18 July 02

Geographic Site: Ambrose channel

Location: Lat/Long 40° 29.77' x 73° 56.18' Vessel: tug: sandmaster
dredge: sandy hook

Weather Conditions: @ 85°F - 92°F
hazy - Front coming through @ 4:30 8 knots S/W calm < 1 ft
hot humid

Water Temperature: Surface _____ Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES (NO)

Comments (type of material, biological specimens, unusual circumstances, etc):

check dashboard: shark's eye (shell only) piece of wood +
couple rocks

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 21 July 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40° 29.72 x 73° 55.85 Vessel: Sandmartin / Sandyhook
10 knots S/S

Weather Conditions: Clear: shoreline haze/humidity. Becoming Sunny 80-85°F 2ftswell

Water Temperature: Surface _____ Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc):
draghead contents: spider crab, & couple rocks

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	

July 19 + 20 did not go out for sand;
Saw another boat was unloading rocks at
our station. fuel run and maintenance.



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 31 July 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°29.68' x 73°55.84' Vessel: Sandy Hook/Sandmaster

Weather Conditions: 93°F Sunny 16kNW 10 Knots → South W. @ 1/2 ft SW

Water Temperature: Surface _____ Below Midwater: _____

Condition of screening apparatus: _____

Incidents involving endangered or threatened species? (Circle) YES **(NO)**

Comments (type of material, biological specimens, unusual circumstances, etc): _____

rock

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 04 03 Aug 02

Geographic Site: Ambrose channel

Location: Lat/Long 40° 29.89' x 73° 56.09' Vessel: Sandmaster/sandyhook

Weather Conditions: <1ft swell 5-10 Knots South low 90's Sunny hazy-shoreline + seaward

Water Temperature: Surface 77°F Below Midwater: 77°F

Condition of screening apparatus: GOOD

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): dropped contents - few rocks

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	

03 Aug 02 - storm the night before blew some power;
Could not unload until power was fixed... later in
the day.



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 05 Aug 02

Geographic Site: Ambrose channel

Location: Lat/Long 40° 29.9' x 73° 56.1' Vessel: Sandy master / Sandy hook

Weather Conditions: low 90's SW 10-15 Knots chance RAIN haze covers shoreline and seaward
1/2 ft swell

Water Temperature: Surface 76° F Below Midwater: 80° F

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES (NO)

Comments (type of material, biological specimens, unusual circumstances, etc):
draghead contents: rock, fishingline, crab (basil like blue)

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>1</u>	<u>1</u>	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 06 Aug 02

Geographic Site: Ambrose channel

Location: Lat/Long 40 30.1' x 73° 57.8' Vessel: Sandmaster / Sandyhook

Weather Conditions: NW 15-20 knots BO's 3-5 ft swell Sunny Windy/Breezy

Water Temperature: Surface _____ Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Nothing

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 07 Aug 02

Geographic Site: Ambrose channel

Location: Lat/Long 40° 29.9' x 73° 56.1' Vessel: Sandmaster/Sandyhook

Weather Conditions: 80's N 10-15 Knots 2ft swell sunny

Water Temperature: Surface 73°F Below Midwater: 72°F

Condition of screening apparatus: GOOD

Incidents involving endangered or threatened species? (Circle) YES **(NO)**

Comments (type of material, biological specimens, unusual circumstances, etc):
few rocks

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 08 Aug 02

Geographic Site: Ambrose channel

Location: Lat/Long 40° 29.8' x 73° 56.0' Vessel: Sandmaster / Sandy hook

Weather Conditions: 30's N 8-10 knots Sunny 1/2 ft swell

Water Temperature: Surface _____ Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Nothing

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	

[illegible]



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 10 Aug 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40° 29.6' N 73° 55.5' W Vessel: Sandmaster/Sandyhook

Weather Conditions: Sunny Mostly 85°F S 8-16 knots 3 ft swell

Water Temperature: Surface 73° Below Midwater: 72°

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES **(NO)**

Comments (type of material, biological specimens, unusual circumstances, etc):
drifted contents of drift wood, few rocks

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 11 Aug 02

Geographic Site: Ambrose channel

Location: Lat/Long 40° 29.85' N 73° 56.08' W Vessel: Sandy master / Sandy hook

Weather Conditions: SSW 10-15 knots 2-4ft swell Sunny 90°F

Water Temperature: Surface 72°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc):
drifted contents: log and piece of wood

Observer's Name: Bennie Brown

Observer's Signature: Bennie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 12 Aug 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40° x 73° Vessel: Sandmaster / Sandy Hook

Weather Conditions: Sunny, hazy humid Low 90's 5-10-15 Knots

Water Temperature: Surface 73° F Below Midwater: 74° F

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES (NO)


Comments (type of material, biological specimens, unusual circumstances, etc):
draghead contents: some rocks

Observer's Name: Bonnie Braun

Observer's Signature: Bonnie Braun

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 27 Aug 02

Geographic Site: Ambrose Channel

Location: Lat/Long 10° 29.6 73° 55.5 Vessel: Budget Sandmaster / Candy Hook

Weather Conditions: Beaufort 5 80°F SE @ 10-15K

Water Temperature: Surface 71°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Dragehead (1) Knobbed whelk
(1) Spider Crab

Observer's Name: TARA Fitzpatrick

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 28 Aug 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40° 31.394 73° 59.961 Vessel: Sandmaster/Sandyhook

Weather Conditions: Beaufort 3, 80°F NE@10K

Water Temperature: Surface 71°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc):
Dragnet - (1) knobbed wheel, (2) shark eye

Observer's Name: TARA FITZPATRICK

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 29 Aug 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40° 31.394 73° 59.941

Vessel: Sandmaster / Sandhook

Weather Conditions: Beaufort 3, 44°F

Water Temperature: Surface 71°F

Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Braghead - (2) Spider crabs
(1) Shark eye


Observer's Name: TARA Fitzpatrick

Observer's Signature: _____

Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 30 Aug 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°31.394 73°59.961

Vessel: Grandmaster / Grandwood

Weather Conditions: Beaufort 3, 75°F SE@5-10K

Water Temperature: Surface 71°F

Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES ☐

☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Brachid - (1) Spider Crab

Observer's Name: TPRA Fitzpatrick

Observer's Signature: _____

[Signature]

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>1</u>	<u>1</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 31 Aug 02

Geographic Site: Ambrise Channel

Location: Lat/Long 10°31.394 73°59.961

Vessel: Grandmaster/Sandyhook

Weather Conditions: Beaufort 6, 70°F NR@23K

Water Temperature: Surface 71°F Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES ☐ **NO** ☒

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Braghead - (1) Spider Crab
(1) Shark Eye

Observer's Name: TARA FITZPATRICK

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>2</u>	<u>2</u>	

[illegible]

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 02 Sept. 02

Geographic Site: Ambrose Channel

Location: Lat/Long 10°31.394 73°59.961 Vessel Sandmaster/Sandhook

Weather Conditions: Beaufort 4 66°F N@10-12

Water Temperature: Surface 71°F Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES ☐ NO ☒

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Dragehead - (1) Shark Eye
(1) Spider Crab


Observer's Name: TARA Fitzpatrick

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	

[illegible]



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 11 Sept 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°31.394 73°59.901

Vessel: Sandmaster/Sandyhook

Weather Conditions: Buoy 3, 82°F SSE@20K

Water Temperature: Surface 70°F

Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES ☐

☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Draghead - (3) herring

Observer's Name: TARA Fitzpatrick

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 12 Sept 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°31.394 73°59.961 Vessel: Sandmaster/Sandyhook

Weather Conditions: Blaugfort 3 82°F SSE @ 10-15K

Water Temperature: Surface 70°F Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____


Braghead - (1) knobbed whelk
(2) Shark Eye

Observer's Name: TARA Fitzpatrick

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>4</u>	<u>4</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 13 Sept 02

Geographic Site: Ambrose Channel

Location: Lat/Long 10°31.394 73°57.961 Vessel Windmaster/Sandypool

Weather Conditions: Beaufort 3, 80°F SW @ 5-8K

Water Temperature: Surface 70°F Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES ☐ NO ☒

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Drumhead - (1) Knobbled whelk
(5) Shark Eye

Observer's Name: TARA Fitzpatrick

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 14 Sept 02

Geographic Site: Ambrose Channel

Location: Lat/Long 70°31.394 73°59.961 Vessel: Sandmaster/Sandyhook

Weather Conditions: Beaufort 3 76°F SW@3-5k

Water Temperature: Surface 70°F Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____


Brayhead - (4) Shark Eye
(1) Starfish

Observer's Name: TARA FITZPATRICK

Observer's Signature: [Signature]

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>4</u>	<u>1</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 15 Sept 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°31.344 43°59.961

Vessel: Sandmaster / Sandyhook

Weather Conditions: Beaufort 4, 43°F SUNNY

Water Temperature: Surface 40°F

Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Dragehead - (3) Knobbled Whelk
(2) Shark Eye

Observer's Name: Theresa Fitzpatrick

Observer's Signature: [Signature]

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 16 Sept 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°31.394 73°59.961 Vessel: Sandmaster/Sandyshook

Weather Conditions: Beaufort 3 78°F 805K

Water Temperature: Surface 78°F Below Midwater: _____

Condition of screening apparatus: good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc):
Brayhead - (2) Shark Eye

Observer's Name: TARA FITZPATRICK

Observer's Signature: Tara Fitzpatrick

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>1</u>	<u>1</u>	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 25 Sept 02

Geographic Site: AMBross Channel

Location: Lat/Long 40°29N 73°55W Vessel: SandMaster/Sandy Hook

Weather Conditions: Beaufort 3, Clear, winds NNE 60°F

Water Temperature: Surface 70°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☐ NO ☒

Comments (type of material, biological specimens, unusual circumstances, etc): _____

STONES, COAL, Fishing Line, Black Mud
Left Dock 2AM Arrived 11:30AM

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 26 Sept 02

Geographic Site: Ambross Channel

Location: Lat/Long 40°31'N 74°01'W Vessel: Sandmaster/Sandy Hook

Weather Conditions: Beaufort scale (4) winds E Cloudy Light Rain 64°F

Water Temperature: Surface 71°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Horseshoe crab, spider crab, rocks, Mud, Fishing line
Lead sinker, net, razor clam shell

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	

[illegible]



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 28 Sept 02

Geographic Site: Ambross Channel

Location: Lat/Long 40°30'N 73°58'W Vessel: Sand Master / Sandy Hook

Weather Conditions: Beaufort Scale 4 winds N Clear sky 71°F

Water Temperature: Surface 70°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Horseshoe crab, 2 lead sinkers, fishing line
rocks, water shells

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 29 Sept 02

Geographic Site: Ambross Channel

Location: Lat/Long 40°29'N 73°56'W Vessel Sand Master / Sandy Hook

Weather Conditions: Beaufort (3) NW Clear 62°F

Water Temperature: Surface 70°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☐ NO ☒

Comments (type of material, biological specimens, unusual circumstances, etc):
rocks, Hermit crab, Windup, wood

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 7 OCT 02

Geographic Site: AmBross Channel

Location: Lat/Long 40°36'N 73°59'W Vessel: Sand Master / Sandy Hook

Weather Conditions: Beaufort 3 SW, cloudy, 72°F

Water Temperature: Surface 67°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc):
1 Horseshoe crab, 4 rocks

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
<u>Ø</u>	<u>Ø</u>	<u>Ø</u>	

Channel is filled with floating wood



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 8 Oct 02

Geographic Site: Ambross channel

Location: Lat/Long 40°29'N 73°55'W Vessel: Sand Master / Sandy Hook

Weather Conditions: Beaufort 4, NE, Clear sky 59°F

Water Temperature: Surface 66°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES **(NO)**

Comments (type of material, biological specimens, unusual circumstances, etc):
HemT crab, rocks, coal

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 9 OCT 02

Geographic Site: Ambross Channel

Location: Lat/Long 40°29'N 73°56'W Vessel: Sand Master/Sandy Hook

Weather Conditions: Beaufort 3, East Cloudy 61°F

Water Temperature: Surface 68°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☐ NO ☒

Comments (type of material, biological specimens, unusual circumstances, etc): _____

ROCKS, Wood, Lady Crab, Horseshoe crab,
Shells, Fishing line + hook

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
<u>✓</u>		<u>✓</u>	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 10 OCT 02

Geographic Site: Ambross Channel

Location: Lat/Long 40°29'N 73°05'W Vessel: Sand Master/Sandy Hook

Weather Conditions: Beaufort 4 East Cloudy w RAIN 64°F

Water Temperature: Surface 67°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc):
Wood, yellow Tee Shirt, Conch shell, rocks

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
<u>Ø</u>		<u>Ø</u>	



Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 11 Oct 02

Geographic Site: Ambross Channel

Location: Lat/Long 40°30'N 73°59'W Vessel: Sand Master/Sandy Hook

Weather Conditions: Beaufort 4, East RAIN 59°F

Water Temperature: Surface 66°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc):
Lead Sinkers, wood, Rocks, Fishing Line

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 12 OCT 02

Geographic Site: Ambross Channel

Location: Lat/Long 40°33N 74°01.5W Vessel: Sand Master / Sandy Hook

Weather Conditions: Beaufort 6 East, RAIN, FOG, 64°F

Water Temperature: Surface 67°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc):
2 Lead Sinkers, cable, Rope, coal, Fishing line

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
<u>/</u>	<u>0</u>	<u>0</u>	



REMSA INC.

Research, Environmental & Management Support

Marine Endangered Species Observer Form

Daily Report

Bridge Watch

Date: 13 Oct 02

Geographic Site: Ambross Channel

Location: Lat/Long 40°30.5N 73°58.6W Vessel: Sand Master Sandy Hook

Weather Conditions: Beaufort 3 west, cloudy light rain 61°F

Water Temperature: Surface 69°F Below Midwater: _____

Condition of screening apparatus: _____

Incidents involving endangered or threatened species? (Circle) YES **(NO)**

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Two Horseshoe crabs, wood, fishing line

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



REMSA INC.

Research, Environmental & Management Support

Marine Endangered Species Observer Form

Daily Report

Bridge Watch

Date: 14 OCT 02

Geographic Site: AMBROSS Channel

Location: Lat/Long 40°39'52"N 73°58'6"W Vessel: Sand Master/Sandy Hook

Weather Conditions: Beaufort 3 North, Clear sky, 61°F

Water Temperature: Surface 66°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES **(NO)**

Comments (type of material, biological specimens, unusual circumstances, etc):
Spider crab, rocks, conch shell, Fishing line + hook

Observer's Name: Thomas Reedy

Observer's Signature: Thomas Reedy

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



REMSA INC.

Research, Environmental & Management Support

Marine Endangered Species Observer Form

Daily Report

Bridge Watch

Date: 10/22/02 22 Oct 02

Geographic Site: Ambrose channel

Location: Lat/Long 40° 29.9' x 73° 56.23' Vessel: Sandmaster / Sandyhook

Weather Conditions: Clear, 49°F-50°F, 2 ft swell 8-14 knots NE

Water Temperature: Surface 63°F Below Midwater: Surface 63°F

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc):

piece of wood, piece of sheet metal, ~~shark~~ crabs, starfish
shark's eye, horseshoe crab

Observer's Name: Bennie Brown

Observer's Signature: Bennie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



REMSA INC.

Research, Environmental & Management Support

Marine Endangered Species Observer Form

Daily Report

Bridge Watch

Date: 23 Oct 02

Geographic Site: Ambrose channel

Location: Lat/Long 40° 29.52' x 73° 55.77' Vessel: Sandy hook / Sandmaster

Weather Conditions: 54°F relatively clear w/ haze on inland 10-16 Knots SW ^{later} (→ NE)
1-2 ft swell

Water Temperature: Surface 61°F Below Midwater: 54°F

Condition of screening apparatus: GOOD

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc):

2 horseshoe crabs, 2 spider crabs, shark eyes, some rocks,
2 pieces of wood,

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.

Research, Environmental & Management Support

Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 24 Oct 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°29.76' x 73°56' Vessel: Sandy hook/sandmaster

Weather Conditions: upper 40's 5 knots N cloudy <1ft swell

Water Temperature: Surface 62°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

rocks, spider crab, "sharks eye" (s)

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	

Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 26 Oct 02

Geographic Site: Ambrase Channel

Location: Lat/Long 40° 32' N x 74° 01.2' W Vessel: Sandyhook/Sandy Master

Weather Conditions: Clear 17-15 knots NW 56°F <1 ft swell

Water Temperature: Surface 58°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☐ NO ☒

Comments (type of material, biological specimens, unusual circumstances, etc):
5 spider/starfish 3 shore crabs; piece of wood.
pieces of plastic, & fishing line

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	

dredged @ 1930 - 2300 (est.)

Marine Endangered Species Observer Form
Daily Report
Bridge Watch

Date: 27 Oct. 02

Geographic Site: Ambrose channel

Location: Lat/Long 40° 29.6' x 73° 55.7' Vessel: Sandyhook/Sandmaster

Weather Conditions: clear NW 13-17 knots 51°F 1 ft swell

Water Temperature: Surface 53°F ^("sea temperature" ... surf acc?) Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc):

2 fishing line with sinkers, lobster claw, concho, "shark's eye"
piece of wood, some rocks. Spider crab

Observer's Name: Bonnie Brown

Observer's Signature: _____

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>Ø</u>	<u>Ø</u>	

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 28 Oct 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40° 29.93' x 73° 56.2' Vessel: Sandmaster / Sandy Hook

Weather Conditions partly cloudy 1-2ft swell NW 16 knots 55°F

Water Temperature: Surface _____ Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc):
2 spider crabs, 2 horseshoe crab, 1 rock, shred of wood

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>2</u>	<u>2</u>	



REMSA INC.

Research, Environmental & Management Support

Marine Endangered Species Observer Form

Daily Report

Bridge Watch

Date: 11/5/02

Date: 11/5/02
Geographic Site: AmBrose Channel

Location: Lat/Long 46° 29' 93" 73° 56' Vessel: Sandmaster

Weather Conditions: Overcast 1-2' swell


Water Temperature: Surface _____ Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc):
Double Sh-Fts - 0900-2100 w/ach ~~3-4~~ w/ach
road 314

Observer's Name: 1 Anna Newberry

Observer's Signature: 

Bridge Watch Summary

[illegible]



Marine Endangered Species Observer Form

Daily Report

Bridge Watch

Date: 11/06/02

Date: 11/10/15

Geographic Site: Amuse Channel

Location: Lat/Long 40° 29' 93" 73° 50' Vessel:

Weather Conditions: lite rain Breezy

Water Temperature: Surface _____ Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES (NO)

Comments (type of material, biological specimens, unusual circumstances, etc):

At Dock 0450-1900 1400-1700 Bridge
watch (d pet) load St-encl: 1604-1704

Observer's Name: Donna Newberry

Observer's Signature: [Signature]

Bridge Watch Summary

[illegible]



Species	# of Sightings	# of Animals	Comments
---------	----------------	--------------	----------



Date: 11/8/02

Location: Lat/Long 40° 29' 73° 55' Vessel: Sandmaster

Water Temperature: Surface _____ Below Midwater: _____


Incidents involving endangered or threatened species? (Circle) YES ☐ NO ☒

Comments (type of material, biological specimens, unusual circumstances, etc.)

Bridge watch 0600-1045 + 1660-1800

Observer's Signature: [Signature]

Species	# of Sightings	# of Animals	Comments
---------	----------------	--------------	----------



[illegible]

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 19 Nov 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40° 29' .67" N 73° 55' .77" W Vessel: SANDY HOOK SANDMASTE

Weather Conditions: Clear - partly cloudy 4/10 F W 12 knots 1 ft swell

Water Temperature: Surface 55°F (Five Island buoy) Below Midwater: _____

Condition of screening apparatus: GOOD

Incidents involving endangered or threatened species? (Circle) YES **(NO)**

Comments (type of material, biological specimens, unusual circumstances, etc):
few rocks (wedged in mesh flushily) Spider crab

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>4</u>	<u>2</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 20 Nov 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°29.67' x 73° 55.77' Vessel: Sandmaster/Sandy Hook

Weather Conditions: <1 ft swell W 8 knots 50°F - mid 50°F's Sunny (clear w/ haze on shore in)

Water Temperature: Surface 55°F (Five Island buoy) Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____


Spider crab.

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 21 NOV 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40°29.67 x 73°55.7 Vessel: Sandyhook/Sandmaster

Weather Conditions: 52°F Cloudy calm → SE 5-10 Knots <1ft swell slightly hazy

Water Temperature: Surface 55°F (Five Is. Buoy) Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____


piece of wood, horseshoe crab, spider crab

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>0</u>	<u>0</u>	



REMSA INC.

Research, Environmental & Management Support

No LOAD Taken, due to weather

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 22 NOV 02

Geographic Site: Ambrose channel

Location: Lat/Long N/A Vessel: Sandyhook / Sandmaster

Weather Conditions: Dense Fog (1^{win} knots Visibility) NE 10 knots

Water Temperature: Surface _____ Below Midwater: _____

Condition of screening apparatus: N/A

Incidents involving endangered or threatened species? (Circle) YES ☐ NO ☒

Comments (type of material, biological specimens, unusual circumstances, etc):
Did not take a load, turned around.
Fog got too thick or thicker.

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	0	0	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 24 NOV 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40° 21.9' N x 73° 56.6' W Vessel: Sandyhook/Sandmaster

Weather Conditions: 50°F ^{GROUND HAZE} Sunny - mostly Sunny W/9 knots 1-3 ft swell

Water Temperature: Surface 54-56°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES (NO)

Comments (type of material, biological specimens, unusual circumstances, etc):
piece of wood, fishing tackle

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>2</u>	<u>2</u>	



REMSA INC.

Research, Environmental & Management Support

**Marine Endangered Species Observer Form
Daily Report
Bridge Watch**

Date: 25 Nov 02

Geographic Site: Ambrose Channel

Location: Lat/Long 40 29.943' x 73 56.462' Vessel: Sandyhook/Sandmaste

Weather Conditions: S 13 knots 54°F Sunny/Partly Cloudy GROUND HAZI
1-3 ft swell

Water Temperature: Surface @ 54°F-56°F Below Midwater: _____

Condition of screening apparatus: Good

Incidents involving endangered or threatened species? (Circle) YES ☒ NO

Comments (type of material, biological specimens, unusual circumstances, etc): _____

Nothing

Observer's Name: Bonnie Brown

Observer's Signature: Bonnie Brown

Bridge Watch Summary

Species	# of Sightings	# of Animals	Comments
	<u>Ø</u>	<u>Ø</u>	